


Soltaro hereby confirms that the below inverters have been tested and are deemed as compliant to AS4777.2-2020, IEC62109-1:2010 and IEC62109-2:2011

- AIO2-INS-5000

Soltaro confirms that all serial numbers later than ESL5102N21070058 shall be updated to correct firmware to be compliant to the above standards before import. All serial numbers previous may require a firmware update, please contact us via email to [service@soltaro.com](mailto:service@soltaro.com) for confirmation if your inverter is affected. If required, firmware updates can be pushed via the remote monitoring portal before install.

Soltaro is acting as the importer for all Soltaro products, contact details have been listed below.

Business Name: The Trustee for Soltaro Unit Trust  
ABN: 78 800 728 807  
Phone: +61 1300 276 582  
Email: [service@soltaro.com](mailto:service@soltaro.com), [info@soltaro.com](mailto:info@soltaro.com)



George Masmeyer  
Technical Manager  
17-12-2021